

- NOTES:
- 1. CONTRACTOR MUST FIELD VERIFY BURY DEPTH PRIOR TO ORDERING HYDRANT AND VALVE.
- 2. EACH HYDRANT MUST INCLUDE A THREADED WEEP HOLE. THE WEEP HOLE SHALL REMAIN OPEN UNLESS GROUNDWATER IS PRESENT OR IF THE HYDRANT IS LOCATED IN A CONTAMINATED AREA.
- 3. HYDRANT COATINGS DAMAGED DURING CONSTRUCTION SHALL BE REPAIRED AFTER THE BITUMINOUS BASE IS INSTALLED. PRIME AND PAINT HYDRANTS PER AWWA AND MANUFACTURER'S STANDARD.
- 4. ALL BOLTS MUST BE BLUE TEFLON COATED.
- 5. THE UPPER AND LOWER STEM MUST BE STAINLESS STEEL 304.
- 6. HYDRANT MUST INCLUDE A HIGH PRESSURE SEAT RING.
- 7. NO HYDRANT EXTENSIONS.

St. Louis Park MINNESOTA HYDRANT		PUBLISH	PLATE	
	St. Louis Park MINNESOTA		DATE	NO.
		HYDRANT	1/20/22	W-4